दूरध्वनी, Tel: 6656 4021 फॅक्स, Fax: 91-(22)-22612404 टेलेक्स : Telex : 81-11-81047 MBPT IN

E-mail: dc@mbptmail.com Visit us at http://www.mumbaiport.gov.in

मुंबई पोर्ट दूस्ट



उप सरंक्षक का कार्यालय, समुद्री विभाग, पोर्ट भवन, १ ला माला, शुरंजी वल्लभदास मार्ग, बॅलार्ड इस्टेट, मुंबई : 400 001.

Deputy Conservator's Office, Marine Department, Port Bhavan, 1ST Floor, Shoorji Vallabhdas Marg, Ballard Estate, Mumbai - 400001.

No.DC/C-Security/ 3806

= 7 AUG 2014

INSA MANSA Shipping Corporation of India All Port Users All Ship Operators, Owners, Managers Manning Agents And Charterers of all types of vessels Masters of all vessels visiting/intending to visit Port of Mumbai All Shipping Agents

> Sub: Usage of Thuraya, Irridum and other such Satellite Communication in Indian Waters.

With reference to this office circular No.DC/C-Security/4451 dated 26.09.2013 and DGS Order No.2 of 2012 dated 17.05.2012, it has been observed that vessels in and around Mumbai Harbours are still using Thuraya Irridum and other Satellite Communication System in Indian Waters, which is prohibited by the above mentioned DGS Order.

It is brought to the notice that any vessel under your agency/ownership should be 2 notified to ensure strict compliance of above order. In case the vessel or the person is in possession of such Satellite Communication Equipment then it is to be declared in the Pre Arrival Notification of Security (PANS) Certificate which is required to be communicated to the following enforcement - agencies atleast 96 hours prior to vessels entering Indian Waters:

The Naval Officer-in-Charge

(Maharashtra)

Headquarters, Maharashtra Naval Area.

SBS Marg, Mumbai - 400 023.

Ph: 22751857, Fax: 22661105

E-mail:

The Commander Coast Guard, Coast Guard Region (West), Golfadevi Temple Road, Prabhadevi P.O. Worli,

Mumbai - 400 035.

Ph: 24379478, Fax: 24379201

E-mail

indsar@vsnl.net.mrcc-

west@indiancoastguard.nic.in