कुलनी/Tel: 6656 4021 फेल (Fax: 91-(22)-22612404 टेलेस : Telax : 81-11-81047 MBPT IN E-mail : <u>do@mbptmail.com</u> Visit us at http://www.mumbaiport.gov.in

मुंबई पोर्ट ट्रक्ट MUMBAI PORT TRUST



ज्य शंक्षक क कार्ताल, बहुती कियान, पोर्ट भवन, र सा पता, बहुती करवापक वर्ग, वेसाई क्षेट्र, वृद्धां : 400 001. Deputy Conservator's Office, Marine Department, Port Bhavan, 1st Floor, Shoorji Vallabhdas Marg, Ballard Estate, Mumbai - 400001.

No.DC/C-NM/ 1668

2 7 APR 2015

LOCAL NOTICE TO MARINERS

INSA
MANSA
ALL TANKER VESSEL OPERATORS, OWNERS, MANAGERS & CHARTERERS
ALL VESSEL OPERATORS, OWNERS, MANAGERS AND CHARTERERS
MASTERS OF ALL VESSELS VISITING/INTENDING TO VISIT MEPT
ALL BULK CARRIERS' OPERATORS, OWNERS, MANAGERS & CHARTERERS
ALL SUPPLY BOATS/TUGS OPERATORS, OWNERS, MANAGERS & CHARTERERS
ALL AGENTS
SHIPPING CORPORATION OF INDIA
ALL PORT USERS
ALL CONCERNED

Sub: Geotechnical investigation in Mumbai Harbour Channel and JN Port Channel.

M.V. Jackup Barge 'Reliable' (No. GMB/MGD/0020) has commenced Geotechnical invistigation in Mumbai Harbour main channel and JN Port channel w.e.f. 20.04.2015, for approximately 45 days.

No	Latitude	Longitude
1	18° 50′ 10.60527″ N	72° 46' 20.74699" E
2	18° 50' 49.61800" N	72° 47' 25.63488" E
3	18° 50' 39.06788" N	72° 47′ 35.36981″ E
4	18° 50' 43.77039" N	72* 47' 48.04730" E
5	18° 50' 53.67627" N	72° 47' 55.29511" E
6	18° 51' 01.83195" N	72° 47' 54.77888" E
7	18° 50' 59. 13897" N	72° 48' 14.55486" E
8	18° 51' 13.10975" N	72° 48' 19.08637" E
9	18° 51' 17.73258" N	72° 48' 44.40332" E
10	18° 51' 24.28763" N	72° 49' 08.19294" E
11	18° 51' 38.64502" N	72° 49' 15.21426" E
12	18° 51' 42.73172" N	72° 49′ 39.34432″ E
13	18° 51' 43.96598" N	72° 49' 53. 16191" E
14	18° 52' 13.93225" N	72° 50' 42.23811" E
15	18° 52' 13.71399" N	72° 50' 48.66274" E

The Geotechnical investigation will commence at Sr. No. 1 location and thereafter move to the other locations. The daily update of the location of Geotechnical investigation will be intimated and promulgated through VIS everyday at 0900 hrs. and will be also brought to the notice of incoming vessels.

All mariners navigating in the Mumbai Harbour and in the vicinity are hereby directed to take serious note of the same while navigating and proceed with slow speed in close proximity of the operational area.

HARBOUR MASTER

22/04/16