कूल्बने/Tel: 6656 4021 फॅना Fax: 91-(22)-22612404 देनेत्स : Telex : 81-11-81047 MBPT IN E-mail : dc@mbptmail.com Visit us at http://www.mumbaiport.gov.in

मुंबई पोर्ट ट्रस्ट MUMBAI PORT TRUST



उप बरंतक का कार्यासय, बनुकी विमान, घोर्ट भवन, १ ला सला, शुस्ती बस्तभद्धव सर्व, बॅसार्ड इस्टेट, न्यं : 400 001. Deputy Conservator's Office, Marine Department, Port Bhavan, 1⁵⁷ Floor, Shoorji Vallabhdas Marg, Ballard Estate, Mumbai - 400001.

2 1 APR 2015

No: DC/C-/C-SH/ 1645

Το, MANSA ALL PORT USERS SHIP AGENTS SHIP OWNERS/CHARTERS

CIRCULAR

Sub: Inner Anchorage berth for 11.7 mtrs. Draft vessel.

Considering the present minimum available depth of 12.5 mtrs. at anchorage area, it has been decided to permit vessels of 11.7 mtrs. draft during monsoon season.

As a prudent mariner, Master of the vessel will:

- 1. Maintain strict anchor water.
- 2. Maintain continuous watch on VHF Ch 12.
- 3. Not allow more than two barges alongside the vessel during cargo operations. -4. Maintain engines on short notice.

Further, agent of the vessel has to provide Letter of Indemnity in the prescribed format on a stamp paper of Rs. 200/- for a vessel with a draft of more than 11.5 mtrs.

- Sularitted for int. of Dy. Comm. Appl.

c.c to P.S. to Chairman for kind information of Chairman.

C.c to P.S. to Dy. Chairman for kind information of Dy. Chairman. c.c. to Principle Officer, Mercantile Marine Department, Mumbai.

c.c. to Nautical Adviser, Government of India.

c.c. to Director General of Shipping.

c.c. to Sr. Dock Master, Indira Dock.

c.c. to Dock Master, Jawahar Dweep and Pirpau }for information

c.c. to Dock Master Control Station

c.c. to VTS Staff

c.c. to Traffic Manager, MbPT

c.c. to Sr. Dy. Director (P&R) with a request to arrange to upload on MbPT website.

CS/flag circular/pg17